

## 8.28 ~AA1

### Description:

Command to reset the watchdog timeout status of the device.

### Command Syntax:

~ <u>AA</u> 1[ <u>CS</u> ](CR)	
~	Delimiter character
<u>AA</u>	Address of the device to be configured in hexadecimal format (00 to FF)
1	Command to reset the watchdog timeout status
[ <u>CS</u> ]	Checksum
(CR)	Carriage Return

### Response:

Valid Command: !AA[CS](CR)

Invalid Command: ?AA[CS](CR)

!	Delimiter for a valid command
?	Delimiter for an invalid command
<u>AA</u>	Address of the device
[ <u>CS</u> ]	Checksum
(CR)	Carriage Return

### Examples:

Send command to reset the watchdog status and return valid response.

Command: ~011(CR)

Response: !01(CR)